

Commonwealth of Virginia Uniform Water Well Completion Report

Owner Raymond Reame
 Address 137 Calverton Rd Fred
 Phone _____
 Location Forest Lane

Tax Map ID 59-56-E
 VDH Permit STDP-00-3415
 WWCB Permit _____
 WWCB ID _____
 County Stafford

Well Data

General Information

Drilling Method Bored Date Completed 6-22-01 Total Depth of Well 51
 Depth to Bedrock _____ Yield _____ (GPM) Length of Test _____
 Static Water Level _____ Stabilized Water Level _____ Natural Flow (Rate) _____
 Well Disinfected (Y or N) Y Disinfectant Used H.T.H. Amount Used 1 cup

Casing

From 0 To 51 From _____ To _____ From _____ To _____
 Size 30 Material concrete Size _____ Material _____ Size _____ Material _____
 Weight / Schedule _____ Weight / Schedule _____ Weight / Schedule _____

Gravel Pack

From 51 To 10 From _____ To _____ From _____ To _____

Grout

From 0 To 10 water level SEE P62 From _____ To _____ From _____ To _____
 Bore Hole Size _____ Bore Hole Size _____ Bore Hole Size _____
 Type _____ Type _____ Type _____
 Method _____ Method _____ Method _____

Water Zones of Screened Intervals

From _____ To _____	From _____ To _____	From _____ To _____
Mash Size _____ Diam _____	Mash Size _____ Diam _____	Mash Size _____ Diam _____
From _____ To _____	From _____ To _____	From _____ To _____
Mash Size _____ Diam _____	Mash Size _____ Diam _____	Mash Size _____ Diam _____

Use Data

Private Well: Domestic Agricultural _____ Industrial _____ Monitoring _____
 Public Well: Community _____ Non Community _____

Abandonment Information

Bored or Dug Wells

Casing Removed, Y or N? _____
 If Y, Depth to which casing was removed: _____
 Depth and Type of Fill: _____
 Source of Fill: _____
 Bentonite Plugs: From _____ to _____ From _____ to _____
 Method of permanently marking location: _____

Wells other than Bored Wells

Casing removed, Y or N? _____
 Depth to which casing was removed: _____
 Applicable, depth(s) and type of gravel/sand fill: _____
 Source of gravel or sand: _____
 Cement: From _____ to _____ From _____ to _____

Aug 30 01 02:35p

08/30/01 MON 10:13 FAX 703 631 0234

Denberry & Davis

0804

Driller's Log

Depth	Description of Formation of Sediment	Remarks
0-15 sandy loam		Reason for not grouting well 30' the Aquifer began at approx 10' did not want to seal off water from coming into well.
15-25 clay loam		
25-51 blue sand		

(Use additional Sheets if necessary)

I certify that the information contained here is true and that the well was installed and constructed in accordance with the permit and further that the well complies with all applicable state and local regulations, ordinances and laws.

Name L & H Co. of Montross

Address 577 Creek Horn Road

Montross, Virginia 22570

Phone 804-493-9643

Driller's Signature

Ronald Hales

Date 8-22-01

Representing L & H Co.

Virginia Contractor's License Number 7701-014004A

Make sure the well driller confirms in writing that the only aquifer suitable for the well lies between 11 and 20 feet. This implies that there are no suitable water zones below 20 feet. I would have him make this clear. In addition, he must show or state that the aquifer begins at 11 feet in order for us to approve a 10 foot grout.